

WITTEN COMPANY INC.

Witten Company, Inc. 8199 N. 116th E. Ave. P.O. Box 269 Owasso, OK 74055

ISO 9001, AS9100 & QSLM CL 2 & 3 CERTIFIED

Tuesday, September 11, 2018

Dear Valued Witten Company, Inc. Customer,

This letter serves as a written notice pursuant to the Safe Drinking Water and Toxic Enforcement Act of 1986 (California Proposition 65) that Witten Company, Inc is providing you with information regarding the presence of chemical or chemicals known to the state of California to cause cancer, birth defects or other reproductive harm in Witten's products.

Because Witten Company, Inc. does not have knowledge of or control over the various ways in which Witten's products may be used in the manufacture of consumer products that are sold or supplied in California, we make no determination as to whether Witten's products may result in an exposure requiring a warning under Proposition 65 to Californians.

Witten Company, Inc. is providing you with the following information for Fasteners manufactured using any of the following raw materials, Solid Film Lubricant and fasteners that have been plated with certain chemicals that may result in a warning under Proposition 65.

California Proposition 65



WARNING

WARNING: Some Witten Company, Inc. products may expose you to one or more of the chemicals listed below which are known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to: www.P65Warnings.ca.gov.

Witten Product	Chemical	CAS#	Listed as Causing
Cadmium Plated	Cadmium	7440-43-9	Cancer
Fasteners			Birth Defects
			Reproductive Toxicity
Stainless Steel	Nickel	7440-02-0	Cancer
Fasteners			
Cadmium Plated	Hexavalent	18540-29-9	Cancer
Fasteners,	Chromium (Cr6)		Birth Defects
Aluminum			Reproductive Toxicity
Fasteners			

Telephone Number: (918) 272-9567 Fax Number: (918) 272-9411

Web Site: http://www.wittenco.com

E-mail: info@wittenco.com

September 13, 2018

Page 2

Carbon Steel	Lead	7439-92-1	Cancer
Fasteners		e e	Birth Defects
			Reproductive Toxicity
			Developmental
		*	Problems
Dry Film	Antimony Trioxide	1309-64-4	Cancer
Lubricants			
Dry Film	Toluene	108-88-3	Reproductive Toxicity
Lubricants			

If you need additional information regarding your parts please contact us at $\underline{info@wittenco.com}$.

Sincerely,

Witten Company, Inc.

Donald Witten

President

Email: quality@wittenco.com